



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

June 16, 2006

Supervisor 

Mine Name: Tejon Quarries

Operator Name:

Rocanville Corporation

Mert Hamilton

PO Box 35

Delta, Utah 84624

Inspector(s): Tom Munson

Other Participants: None

Mine Status: Active

Permit number: M270087

Inspection Date: 4-11-2006

Time: 1 PM

Weather: Sunny

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

To determine the amount of mining related disturbance currently being mined.

Directions to Site:

In North Canyon West of Delta, Utah

Inspection Summary:


The four quarries were GPS'ed and there was a crew of people splitting rock and stockpiling rock onsite

Conclusions and Recommendations:

Overall, the site had not changed significantly and it is under an interim contract and reclamation bonding schedule for 11.5 acres of disturbance. The site has not received its final Large Mine Permit and is currently operating under an interim permit until the bonding is complete. The site is at exactly



Inspection Date: May 11, 2006; Report Date: June 11, 2006
Page 2 of 2
M/027/087


11.5 acres, therefore it is necessary to watch that the site does not expand beyond its current bonding liability.



Inspector's Signature  **Date:** June 16, 2006

Tm:pb


cc: Mert Hamilton
BLM, Fillmore office, Jerry Mansfield
Attachment: GPS & Photos
O:\M027-Millard\M0270087-Tejon\inspections\insp04112006.doc




































Mine Number: M0270087
Mine Name: Tejon Quarries
Township 18 S Range 13 W Section 30 SLBM

Inspection Date Apr. 11, 2006
 Map Produced by DKS

Acres Disturbed	11.58
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0


Total Acres Disturbed	11.58
------------------------------	--------------

Acres Released	0
Acres Excluded	0.95
Acres PreExisting	0
Acres Prelaw	0

Legend
 All items symbolized in legend may not be appear on map

- | | |
|-----------------|---|
| County Boundary | Township or range Line |
| Access | Township or range line: location doubtful |
| Mine | Section line |
| NonMine | Section line: location doubtful |
| Other | Disturbed |
| Interstate | Regraded |
| US Route | Seeded |
| State Route | Released |
| Primary Route | Excluded |
| Secondary Route | PreExisting |
| Main Dirt Road | Prelaw |
| Unimproved Road | Bond Area |
| Interchange | STLA Mineral Leases |
| Trail | BLM Salable Minerals |
| | Community Pit |

DOQ imagery date 1998



0 625
 Feet
 1:7,500 1 inch equals 625 feet
 Verify Scale

Dept. of Natural Resources
 Division of Oil, Gas, and Mining
 Mineral Mines Program

Different data sources and input scales
 may cause misalignment of data layers.
 This product may not meet DOGMA
 standards for accuracy and content.